

## **BLOC À COLONNES**


## 201.23.







## Mode de guidage



## Bloc à colonnes 201.23.

Surface	de	travai
Juliace	ac	uavai

	our lace as travair															
N° de commande Partie 1*	a <sub>1</sub> x b <sub>1</sub>	$a_2$	$b_2$	C <sub>1</sub>	C <sub>2</sub>	C <sub>3</sub>	C <sub>4</sub>	C <sub>8</sub>	$d_2$	dз	е	e <sub>1</sub>	f	I	r	M
201.23.100.080.	100 x 80	140	120	50	30	50	22	15	25	24	100	175	98	160 - 500	30	20x1.5
201.23.125.100.	125 x 100	165	140	50	40	60	22	15	25	24	125	206	118	160 - 500	30	24x1.5
201.23.160.100.	160 x 100	200	140	50	40	60	22	15	25	24	160	229	118	160 - 500	30	24x1.5
201.23.160.125.	160 x 125	200	165	56	40	60	27	15	32	30	160	259	148	180 - 500	37	24x1.5
201.23.200.125.	200 x 125	240	165	56	40	60	27	15	32	30	200	286	148	180 - 500	37	24x1.5
201.23.250.160.	250 x 160	290	200	56	50	70	27	15	32	30	250	346	184	200 - 500	37	30x2

<sup>\*</sup>Numéro de commande partie 2 = compléter le type de guidage et le type/la longueur de la colonne de guidage Exemple de commande, voir début du chapitre A Châssis à colonnes en fonte